

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/10/2018

Submitted Date:

07/13/2018

Document Number:

689801355**FIELD INSPECTION FORM**

Loc ID 314522 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 82440Name of Operator: STEHLE OIL COMPANYAddress: P O BOX 1577City: CRAIG State: CO Zip: 81626**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|---------------|----------------|----------------------------------|---------|
| Neidel, Kris | | kris.neidel@state.co.us | |
| Stehle, Cary | (970) 824-6909 | carystehle@gmail.com | |
| Leonard, Mike | | mike.leonard@state.co.us | |
| | | dnr_cogccenforcement@state.co.us | |
| | | dnr_cogccengineering@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|
| 228908 | WELL | SI | 09/08/2014 | OW | 103-05906 | PINNACLE UNIT 12-30 | WK |

General Comment:FIU MIT witness.

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

| Type | Area | Volume | | |
|--------------------|---|--------|--|------------------|
| PW/CO | | | | |
| Comment: | Stained soil on tank berm. | | | |
| Corrective Action: | Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff. | | | Date: 08/13/2018 |

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected FacilitiesFacility ID: 228908 Type: WELL API Number: 103-05906 Status: SI Insp. Status: WK**Workover**Comment: Inspector on location to witness MIT. Operator was unable to maintain pressure. Test failed.Corrective Action: Contact dnr_cogccengineering@state.co.us with resolution plan.Date: 07/27/2018**COGCC Comments**

| Comment | User | Date |
|---|----------|------------|
| Inspector on location to witness MIT. A follow up inspection to previous inspections as well as this MIT witness, will be performed after workover removal. | waldrone | 07/13/2018 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 401702926 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4523446 |
| 689801357 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4523438 |