

Inspection Photos
Location Name: Joker / 36-9-62
Location #: 417683



Photo #1

Joker 36-9-62 (API # 05-123-31719) tank battery

Stained tank, weeds



Photo #2

Joker 36-9-62 (API # 05-123-31719) Gas meter run

Weeds



Inspection Photos
Location Name: Joker / 36-9-62
Location #: 417683



Photo #3

Joker 36-9-62 (API # 05-123-31719)
Candlestick flare battery



Photo #4

Joker 36-9-62 (API # 05-123-31719)
Disconnected flare ignition wire

Inspection Photos
Location Name: Joker / 36-9-62
Location #: 417683




Photo #5

Joker 36-9-62 (API # 05-123-31719) ECD

Closed inlet valve



Photo #6

Joker 36-9-62 (API # 05-123-31719) ECD

Closed supply gas valve

Inspection Photos
Location Name: Joker / 36-9-62
Location #: 417683



Photo #7

Joker 36-9-62 (API # 05-123-31719) ECD

Ignition Control appears to have no power



Inspection Photos
Location Name: Joker / 36-9-62
Location #: 417683

FLIR Video attachment appears to confirm venting through candlestick flare.
See at following time intervals of video:

- 0:00:30 – 0:00:38
- 0:01:02 – 0:01:08
- 0:01:35 – 0:01:59

Photo #8

Joker 36-9-62 (API # 05-123-31719)

Candlestick flare video from FLIR camera

July 24, 2018

(Will be the 3rd attachment on FIR # 691200294)

