

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/16/2018

Submitted Date:

08/16/2018

Document Number:

691300432**FIELD INSPECTION FORM**Loc ID 429132 Inspector Name: Kraich, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10459Name of Operator: EXTRACTION OIL & GAS INCAddress: 370 17TH STREET SUITE 5300City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Kraich, Adam	970-420-0536	Adam.Kraich@state.co.us	(Area 117) Field Operations
Leonard, Mike		mike.leonard@state.co.us	
Adamczyk, Megan		megan.adamczyk@state.co.us	
,		COGCCInspections@extracti onog.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
450538	WELL	PR	11/30/2017	OW	123-44770	HFE 2	PR

General Comment:

Inspected Facilities			
Facility ID: <u>450538</u>	Type: <u>WELL</u>	API Number: <u>123-44770</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment: <u>PR</u>			
Corrective Action:		Date:	
Complaint			
Comment:	<p><u>Inspection in response to complaint.</u></p> <p><u>Field Inspector Assigned: Adam Kraich</u></p> <p><u>Complaint Received:</u></p> <p><u>Date: 8/15/2018</u></p> <p><u>Complaint Contacted:</u></p> <p><u>Date: 8/15/2018 @16:33</u></p> <p><u>Location #: 429132</u></p> <p><u>Inspection Document #: 691300432</u></p> <p><u>Nature of complaint: Noise</u></p> <p><u>Field Inspector Actions:</u></p> <p><u>On 8/15/2018, I received a complaint in regard to noise on the HFE 22-P location, owned and operated by Extraction Oil & Gas.</u></p> <p><u>On 8/16/2018, I visited the HFE 22-P location and performed a sound audit 350' south of the suspect source of noise complaint; two trailer mounted gas/electric turbines producing a continuous noise described as a shrill. The sound audit was performed at 40.29346, -104.99552 8/16/2018 @ 09:29am. Resulting sound data shows an A-scale sound average of 66.1 db.</u></p> <p><u>It should be noted however, the location appears to have recently had sound walls taken down.</u></p> <p><u>Violation of COGCC rule 802.</u></p> <p><u>All information reviewed and site inspection information were submitted to the complaint specialist for further review.</u></p>		
Corrective Action:	<u>Comply with Rule 802. Identify and install control measures..</u>		Date: <u>08/18/2018</u>

COGCC Comments		
Comment	User	Date
<u>Inspection in response to complaint.</u>	kraicha	08/16/2018
<u>While no official complaint was filed in regard to lighting, permanant lighting fixtures were observed to be facing the south towards nearby neighborhoods. Please ensure light fixtures are pointed as downward as safely possible, especially southern facing fixtures.</u>		

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
691300433	Sound Audit	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4554196
691300434	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4554197