

**FORM
INSP**Rev
X/15

State of Colorado Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

09/07/2018

Submitted Date:

09/07/2018

Document Number:

691200425**FIELD INSPECTION FORM**
 Loc ID 306312 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10110Name of Operator: GREAT WESTERN OPERATING COMPANY LLCAddress: 1001 17TH STREET #2000City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:14 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
,		cogccinspections@gwogco.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287755	WELL	PR	05/01/2018	GW	123-24412	CACHE 8-34	SI

General Comment:

This is a WELL & BATTERY Inspection. Follow-up inspection to FIR #691200244 dated 7/11/2018.

Location			
Lease Road:			
Type	Access		
comment:	Adequate. Gravel & 2-Track Ag road.		
Corrective Action	L		Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Wellhead sign has been posted. This addresses the CA from FIR #691200244 dated 7/11/2018.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Emergency contact number been posted. Verified that the number was answered by a person. This addresses the CA from FIR #691200244 dated 7/11/2018.		
Corrective Action:			Date:
Good Housekeeping:			
Type	TRASH		
Comment:	Trash (Bucket with oily fluid, oily rag, old tools, fittings) inside of east separator doghouse. Refer to Rules 603.f & 907.e for guidance.		
Corrective Action:	Comply with Rule 603.f & 907.e. The previous CA date for this from FIR #691200244 dated 7/11/2018 remains applicable.		Date: 07/23/2018
Type	OTHER		
Comment:	Gas jack compressor has been disconnected and moved from soil pad. Stained soil appears to have been remediated. This addresses the CA from FIR #691200244 dated 7/11/2018.		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment: <input type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Iron panel fence.		
Corrective Action:			Date:

Type			
Comment:	Refer to previous FIR #691200244 dated 7/11/2018 for additional fencing info.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:	Observed wellhead motor valve hissing & venting. Notified crew on site who then made repairs. Venting ceased. Rule 605.d regarding mechanical conditions has been complied with.		
Corrective Action:		Date:	
Type:	#		
Comment:	Refer to previous FIR #691200244 dated 7/11/2018 for additional equipment info.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
			CENTRALIZED BATTERY		40.499062,-104.461664	
Comment:	This centralized battery serves 6 locations (306312, 306310, 306311, 309823, 309973, 419186). Refer to previous FIR #691200244 dated 7/11/2018 for Tanks & Berms info.					
Corrective Action:		Date:				

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:		Date:		

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 287755 Type: WELL API Number: 123-24412 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI. Observed well shut in at separator.

Corrective Action: _____

Date: _____

BradenHeadComment: Bradenhead appears to be plumbed to surface.

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401757336	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4573623
691200427	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4573620