FORM INSP Rev

X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



CLOUGH RWF 313-15

Inspection Date: 10/04/2018
Submitted Date: 10/04/2018
Document Number: 689302060

FIELD INSPECTION FORM

Loc ID	Inspector Na	me: On-Sit		On-Site Inspection		Status Summary:			
335067	Holtz, Darin		2/	2A Doc Num:		THIS IS A FOLLOW UP INSPECTION			
Operator II	nformation:					X	OLLOW UP INSPECTION REC	QUIRED	
OGCC One	erator Number:	96850					NO FOLLOW UP INSPECTION	REQUIRED	
	_					Find	inas:		
Name of O	perator: TEP ROC	JKY MOUN	TAIN LLC						
Address: F	PO BOX 370					15	Number of Comments		
_						1	Number of Corrective Action	S	
City:	PARACHUTE	State:	CO	Zip: 81	635	X	orrective Action Response Request	ed	
Contact In	formation:					-			
Contact Name Phone			ie	Email			Comment		
Rocky, TEP			COGCCInspectionReports erraep.com		s@t All Inspections				
Inspected	Facilities:	-						,	
Facility ID	Туре	Status	Status Date	Well Class	API Num	1	Facility Name	Insp Status	
258902	WELL	PR	01/04/2001	GW	045-0766	67	CLOUGH RWF 13-15	PR	
284588	WELL	PR	05/05/2006	GW	045-122	16	CLOUGH RWF 312-15	PR	
284589	WELL	PR	05/05/2006	GW	045-122	15	CLOUGH RWF 512-15	PR	
284590	WELL	PR	05/05/2006	GW	045-122	14	CLOUGH RWF 412-15	PR	
288170	WELL	PR	11/30/2006	GW	045-1316	64	CLOUGH RWF 443-16	PR	
288171	WELL	PR	11/30/2006	GW	045-1316	35	CLOUGH RWF 43-16	PR	

General Comment:

288172

Routine Field Inspection

WELL

PR

04/11/2007

GW

045-13166

PR

<u>Location</u>								
Lease Road:								
Туре	Access							
comment:								
Corrective ActionL						Date:		
Overall Good: 🔀	Overall Good: ズ							
Emergency Contact N	Emergency Contact Number:							
Comment:	1-970-285-9377							
Corrective Action:						_ Date:		
Good Housekeeping	<u> </u>] <u>:</u>							
Туре	WEEDS							
	uncontrolled weeds on lo	cation.						
Corrective Action:	Comply with Rule 603.f .					Date:	10/16/2018	
Overall Good:								
Spills:								
Туре	Area	Volume						
		volume						
In Containment: N	No							
	Comment:							
Multilple Spills and Releases?								
encing/:								
Туре	WELLHEAD							
Comment:	Hog panel fence							
Corrective Action:					Date:			
Туре	SEPARATOR							
Comment:	: Hog panel fence.							
Corrective Action:					Date:			
Туре	DE TANK BATTERY							
Comment:	Comment: Hog panel fence							
Corrective Action:	1:					Date:		
Equipment: corrective					corrective date			
Type: Horizontal Hea	ted Separator #	7						
Comment	Comment:							
Corrective Action:					Date:			
Type: Bird Protectors # 5								
Comment	nent:							
Corrective Action:	ction:					Date:		
Type: Plunger Lift	ft # 7							
Comment	Comment:							
Corrective Action:	ve Action:					Date:		

Inspector Name: Holtz, Darin Tanks and Berms: Contents Capacity Tank ID SE GPS Type 200 BBLS STEEL AST CONDENSATE Comment: centralized battery Corrective Action: Date: **Paint** Condition Adequate Other (Content) Other (Capacity) Other (Type) **Berms** Туре Capacity Permeability (Wall) Permeability (Base) Maintenance Metal Walls Sufficent **Base Sufficient** Adequate Adequate Comment: Corrective Action: Date: SE GPS Contents Capacity Type Tank ID PRODUCED WATER 200 BBLS STEEL AST Comment: Corrective Action: Date: **Paint** Condition Adequate Other (Content) Other (Capacity) Other (Type) <u>Berms</u> Capacity Туре Permeability (Wall) Permeability (Base) Maintenance Comment: Corrective Action: Date: Venting: Yes/No NO Comment: Corrective Action: Date: Flaring:

Date Run: 10/4/2018 Doc [#689302060]

Comment:

Corrective Action:

Type

Date:

				Inspecte	d Facilities				
acility ID:	258902	Type: _	WELL	API Number:	045-07667	Status: _	PR	Insp. Status:	PR
				Produc	ing Well				
С	omment: We	II Producing	on plunger lift						
Correctiv	e Action:							Date:	
acility ID:	284588	Type: _	WELL	API Number:	045-12216	Status: _	PR	Insp. Status:	PR
				Produc	ing Well				
С	omment: We	II Producing	on plunger lift						
Correctiv	e Action:							Date:	
Facility ID:	284589	Type: _	WELL	API Number:	045-12215	Status: _	PR	Insp. Status:	PR
				Produc	ing Well				
С	omment: We	II Producing	on plunger lift						
Correctiv	e Action:							Date:	
Facility ID:	284590	Type: _	WELL	API Number:	045-12214	Status: _	PR	Insp. Status:	PR
				Produc	ing Well				
С	omment: We	Il Producing	on plunger lift						
Correctiv	e Action:							Date:	
acility ID:	288170	Type: _	WELL	API Number:	045-13164	Status: _	PR	Insp. Status:	PR
0	ommont: Mo	II Droduoina	on plunger lift	Produc	ing Well				
		ii Producing	on plunger lift						
Correctiv	e Action:							Date:	
acility ID:	200474	Turnou	\\/\\\\	ADI Number	045 12165	Ctatus	DD	Inon Status	DD
	288171	Type: _	WELL	API Number:	045-13165 ing Well	Status: _	PR	Insp. Status:	PR
C	omment: We	Il Producino	on plunger lift	Produc	<u>ing wen</u>				
			- Triplangor int						
Correctiv	e Action:							Date:	
Facility ID:	288172	Type:	WELL	API Number:	045-13166	Status:	PR	Insp. Status:	PR
acility ID	200172	туре			ing Well			msp. Status.	
C	omment: We	II Producing	on plunger lift	FIGUUC	<u> </u>				
			on plunger lift						
Corrective	e Action:							Date:	

Inspector Name: Holtz, Darin

Environmental

Spill/Remediation:

Comment:

Corrective Action:

Emission Control Burner (ECB): NO

Comment:

Pilot: Wildlife Protection Devices (fired vessels): YES

		<u>I (O O I CITIC</u>	Reclamation - Storm Water - Pit						
Storm Water:									
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment			
Retention Ponds									
Seeding									
Berms									
Ditches									
		Gravel							
		Compaction							
Comment:			•]			
Corrective Action:									
Pits: NO SURFACE INDICATION OF PIT									

Attached Documents

You can go to COGCC Images (https://cogcc.state.co.us/weblink/) and search by document number:

Document Num	Description	URL
689302061	Inspection photo 689302061	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4598604

Date Run: 10/4/2018 Doc [#689302060]