

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/04/2018

Submitted Date:

10/05/2018

Document Number:

688400360**FIELD INSPECTION FORM**Loc ID 320339 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 31257Name of Operator: FRITZLER RESOURCES INCAddress: P O BOX 114City: FORT MORGAN State: CO Zip: 80701**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:19 Number of Comments7 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Fritzler, Gene	(970) 867-9388	gfritzler@bresnan.net	All Inspections
Gillette, Kira		kira.gillette@state.co.us	
Gomez, Jason		jason.gomez@state.co.us	
Ash, Margaret		margaret.ash@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203490	WELL	PR	12/01/2017	OW	001-09050	BADGER OIL 1	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil under load out line for crude oil tanks		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e	Date:	11/05/2018
Type	TRASH		
Comment:	Trash and unused buckets in serperator house		
Corrective Action:	Comply with Rule 603.f .	Date:	10/19/2018
Type	UNUSED EQUIPMENT		
Comment:	Unused flow back tank by wellhead		
Corrective Action:	Comply with Rule 603.f .	Date:	10/22/2017
Type	OTHER		
Comment:	Stained soil around WH		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e	Date:	11/05/2018
Type	OTHER		
Comment:	Stained soil in front of crude oil tanks		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e	Date:	11/05/2018

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	PIT		

Comment:	hog wire		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Half barbwire and half hog fence		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	barbwire		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	barbwire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	gas powered motor		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		,	
Comment:	Placard faded and not visable. Sign not legible					
Corrective Action:	Install sign to comply with Rule 210.e.					Date: 11/05/2018

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	2210BBL	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate

Comment:							
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
CRUDE OIL	3	300 BBLs	STEEL AST		,		
Comment:							
Corrective Action:						Date:	

Paint

Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate			
Comment:							
Corrective Action:						Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	203490	Type:	WELL	API Number:	001-09050	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NO

Pit ID: _____

Lat: _____

Long: _____

Reference Point: _____

Other: _____

Length: _____

Width: _____

Lining:

Liner Type: _____

Liner Condition: _____

Comment: Birms in disrepair, birms do not have 2' of free board

Corrective Action

Location is within an exception zone, repair or install berms or other secondary containment devices per Rule 604.c.(3)B.

Date: 10/26/2018**Fencing:**Fencing Type: Panel

Fencing Condition: _____

Comment: Hog panels

Corrective Action

Date: _____

Netting:

Netting Type: _____

Netting Condition: _____

Comment: _____

Corrective Action

Date: _____

Anchor Trench Present: _____

Oil Accumulation: _____

2+ feet Freeboard: _____

Comment: _____

Corrective Action

Date: _____

COGCC Comments

Comment	User	Date
This is a follow up inspection on DOC # 685503909 Unused flow back tank is still not in compliance to COGCC rules. Birms on Produced water pits do not have 2' of free board.	silverr	10/05/2018

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
401785263	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4599173
688400361	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4599172