

Inspection Photo
Downing 24-22-6S-94W
API # 045-06633
Inspection # 689302116



Location Photo #1



Location Photo #2, Inaccurate wellhead sign.



Inspection Photo
Downing 24-22-6S-94W
API # 045-06633
Inspection # 689302116



Location Photo #3, Uncontrolled weeds on location.



Location Photo #4, Uncontrolled weeds on location.

Inspection Photo
Downing 24-22-6S-94W
API # 045-06633
Inspection # 689302116



Location Photo #5, Rutted access road



Location Photo #6, Rutted access road

Inspection Photo
Downing 24-22-6S-94W
API # 045-06633
Inspection # 689302116



Location Photo #7, Rutted access road



Location Photo #8, Rutted access road

Inspection Photo
Downing 24-22-6S-94W
API # 045-06633
Inspection # 689302116



Location Photo #9, Rutted lease access road



Location Photo #10, Rutted lease access road.