

# Inspection Photos

Operator: BP Production

API: 05-067-07868

Date: 10/05/2018



**Photo 1. View of the project area from the southern edge facing center**



**Photo 2. View of the southern project area from the southwestern corner facing eastward. Revegetation is progressing within the interim reclamation areas with shrubs such as rabbitbrush (*Chrysothamnus nauseosus*), and grasses such as western wheatgrass (*Pascopyrum smithii*) and sand dropseed (*Sporobolus cryptandrus*).**



**Photo 3. View of Russian thistle (*Salsola tragus*) debris within the southern portion of the working area facing eastward.**



**Photo 4. View of cement debris approximately 2 feet wide and 5 feet long within the southern project area.**



**Photo 5. View of headcut erosion, approximately 5 feet deep in the southwestern project area, needs stabilization.**



**Photo 6. View of the eastern project area from the southeastern corner facing northward.**



**Photo 7. View of an area in the southeastern project area where concentrated stormwater flows exit the well pad, creating a headcut approximately 3 feet wide and deep that flows through dense rabbitbrush shrubs.**