

Inspection Photos

11/19/2018

Operator: FOUNDATION ENERGY
MANAGEMENT LLC - 10112

Location ID: 327492

Inspection Doc. Number: 682504197
Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: FOUNDATION ENERGY MANAGEMENT LLC - 10112
Location ID: 327492



Photo 1: 2013 Google Earth aerial imagery. Photo shows aerial image of the tank battery and various equipment on site.



Photo 2: Photo taken from the south end of the battery location facing west. Photos 2-4 provide an overview of the location from west, north, to east. Photos also show operator has failed to remove equipment and conduct reclamation of the location.

Inspection Photos
Operator: FOUNDATION ENERGY MANAGEMENT LLC - 10112
Location ID: 327492



Photo 3: See Comments under photo 2.

Inspection Photos
Operator: FOUNDATION ENERGY MANAGEMENT LLC - 10112
Location ID: 327492



Photo 4: See comments under photo 2.




Photo 5: Photo taken from the battery location, facing north. Photo shows operator has failed to remove equipment within 3-months of plugging the well.

Inspection Photos
Operator: FOUNDATION ENERGY MANAGEMENT LLC - 10112
Location ID: 327492



Photo 6: Photo taken from the west end of the battery location, facing east. Photo shows pits appear to have been closed.



Photo 7: Photo taken from the battery location, facing north. Photo shows operator has failed to remove equipment from the location per 603.f and 1004.a.



Photo 8: Photo taken from the battery location, facing northeast. See comments under photo 7

Inspection Photos
Operator: FOUNDATION ENERGY MANAGEMENT LLC - 10112
Location ID: 327492



Photo 9: Photo taken from the battery location, facing north. See comments under photo 7



Photo 10: Photo taken from the battery location, facing northeast. See comments under photo 7



Photo 11: Photo taken from the battery location, facing north. See comments under photo 7



Photo 12: Photo taken from the battery location, facing north. Photo shows "Foundation" sign amongst debris on site.

Inspection Photos
Operator: FOUNDATION ENERGY MANAGEMENT LLC - 10112
Location ID: 327492



Photo 13: Photo taken from the battery location, facing east. See comments under photo 7

Inspection Photos
Operator: FOUNDATION ENERGY MANAGEMENT LLC - 10112
Location ID: 327492



Photo 14: Photo taken from the battery location, facing north. See comments under photo 7

Inspection Photos
Operator: FOUNDATION ENERGY MANAGEMENT LLC - 10112
Location ID: 327492



Photo 15: Photo taken from the battery location, facing east. See comments under photo 7



Photo 16: Photo taken from the battery location, facing north. Photo shows tank laying on side. Base of tank appears to have a hole. Photo also shows contaminated soils at tank base.



Photo 17: Photo taken from the battery location, facing north. Photo shows tank laying on side. Base of tank appears to have a hole. Photo also shows contaminated soils at tank base.



Photo 18: Continued from photo 17. Photo shows contaminated soils at tank base.



Photo 19: Photo taken from the battery location, facing southeast. See comments under photo 7

Inspection Photos
Operator: FOUNDATION ENERGY MANAGEMENT LLC - 10112
Location ID: 327492



Photo 20: Photo taken from the battery location, facing east. See comments under photo 7. Photo also shows a barrel filled with chemical not in secondary containment.




Photo 21: Label on barrel in photo 20



Photo 22: Photo taken from the battery location, facing west. See comments under photo 7

Inspection Photos
Operator: FOUNDATION ENERGY MANAGEMENT LLC - 10112
Location ID: 327492



Photo 23: Photo taken from the battery location, facing west. See comments under photo 7



Photo 24: Photo taken from the battery location, facing north. Photo shows tank appears to have been leaking as contaminated soils evident at tank base.



Photo 25: See comments under photo 25.



Photo 26: Photo taken from the battery location, facing north. See comments under photo 7



Photo 27: Photo taken from the battery location, facing east. See comments under photo 7

Inspection Photos
Operator: FOUNDATION ENERGY MANAGEMENT LLC - 10112
Location ID: 327492



Photo 28: Photo taken from the battery location, facing north. See comments under photo 7



Photo 29: Photo taken from shed in photo 28. Multiple documents from the operator “Diversified Operating Corp” were observed within the building. Diversified was a previous operator for this location. Photo shows sheds observed on the east are associated with oil and gas.