

Inspection Photo (s)
Couey 31-2
API # 05-045-07843
Inspection # 6893026037



Location Photo #1



Location Photo #2



Inspection Photo (s)
Couey 31-2
API # 05-045-07843
Inspection # 6893026037



Location Photo #3

Inspection Photo (s)
Couey 31-2
API # 05-045-07843
Inspection # 6893026037



Location Photo #4, Oil stained rock in battery containment.



Location Photo #5, Oil stained rock in battery containment.