

Inspection Photos

12/19/2018

Operator: ST CROIX OPERATING INC # 81490

Location ID: 458423

Inspection Doc. Number: 682504291

Washington County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: ST CROIX OPERATING INC # 81490
Location ID: 458423




Photo 1: Aerial image of construction location. A disturbance area of 2.48 acres was mapped on 12/19/2018 using a Trimble Juno 3B handheld device; this appears to exceed the permitted 2A disturbance area of 2 acres.



Photo 2: Photo taken from the southwest end of the construction disturbance, facing north. Photo provides an overview of the location. Photo also shows that perimeter stormwater and erosion control BMPs have not been installed in accordance with good engineering practices prior to and during construction activities.



Photo 3: Photo taken from the southwest end of the construction disturbance, facing east. Photo provides an overview of the location. Photo also shows that perimeter stormwater and erosion control BMPs have not been installed in accordance with good engineering practices prior to and during construction activities.



Photo 4: Photo taken from the southwest end of the construction disturbance, facing southeast. Photo provides an overview of the location. Photo also shows that perimeter stormwater and erosion control BMPs have not been installed in accordance with good engineering practices prior to and during construction activities. Photo also shows topsoil stockpile



Photo 5: Photo taken from the southeast end of the construction disturbance, facing northwest. Photo provides an overview of the location. Photo also shows that perimeter stormwater and erosion control BMPs have not been installed in accordance with good engineering practices prior to and during construction activities. Photo also shows topsoil stockpile



Photo 6: Photo taken from the southeast end of the construction disturbance, facing north. Photo provides an overview of the location. Photo also shows that perimeter stormwater and erosion control BMPs have not been installed in accordance with good engineering practices prior to and during construction activities. Photo also shows topsoil stockpile



Photo 7: Photo taken from the southeast end of the construction disturbance, facing north. Photo provides an overview of the location. Photo also shows that perimeter stormwater and erosion control BMPs have not been installed in accordance with good engineering practices prior to and during construction activities. Photo also shows topsoil stockpile



Photo 8: Photo taken from the northeast end of the construction disturbance, facing southwest. Photo provides an overview of the location. Photo also shows that perimeter stormwater and erosion control BMPs have not been installed in accordance with good engineering practices prior to and during construction activities.



Photo 9: Photo taken from the northeast end of the construction disturbance, facing northwest. Photo provides an overview of the location. Photo also shows that perimeter stormwater and erosion control BMPs have not been installed in accordance with good engineering practices prior to and during construction activities.



Photo 10: Photo taken from the northwest end of the construction disturbance, facing east. Photo provides an overview of the location. Photo also shows that perimeter stormwater and erosion control BMPs have not been installed in accordance with good engineering practices prior to and during construction activities.



Photo 11: Photo taken from the northwest end of the construction disturbance, facing southwest. Photo provides an overview of the location. Photo also shows that perimeter stormwater and erosion control BMPs have not been installed in accordance with good engineering practices prior to and during construction activities.



Photo 12: Photo taken from the access road, on the southwest end of the location, facing east. Photo shows fill material appears to have been brought onto the location to construct access road.