FORM INSP Rev

X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date: 02/20/2019 Submitted Date: 02/20/2019

Document Number:

FIELD INSPECTION FORM

| FIELD INSPECTION FORM | | | | | | | | | <u>68</u> | <u>89702679</u> |
|-------------------------------|---|-----------|-------------|--|------------|------------|--------------------------------|--------------------------------|-----------|-----------------|
| Loc ID | c ID Inspector Name: | | On-Site I | On-Site Inspection | | | Status Summary: | | | |
| 334850 LONGWORTH, MIKE | | | 2 <i>P</i> | 2A Doc Num: | | | THIS IS A FOLLOW UP INSPECTION | | | |
| Operator II | nformation: | | | | | | F(| OLLOW UP INSPECTI | ON REQU | IRED |
| - | | | | | | | O FOLLOW UP INSPE | CTION RE | EQUIRED | |
| | oerator: TEP ROC | | TAINTI C | | | | Findi | ngs: | | |
| | 7E1 100 | JICT WOON | 17(114 EEO | 11 Number of Comme | | | | | nts | |
| Address: F | PO BOX 370 | | | | | | 0 | — Number of Corrective | e Actions | |
| City: | PARACHUTE | State: | СО | Zip: | 8163 | 5 | Co | — orrective Action Response | Requested | |
| | ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE | | | | | | | HAVE NOT | | |
| Contact In | Contact Information: | | | | | | | | | |
| Contact Name Phone | | ie | Email | | | | Comment | | | |
| Kellerby, Shaun | | | | shaun.ke | llerby@ | estate.co. | .us | | | |
| Inspection, Terra TEP 970-285 | | | 285-9377 | 5-9377 COGCCInspectionRepor erraep.com | | | ts@t | | | |
| Inspected | Facilities: | | | | | | | | | |
| Facility ID | Туре | Status | Status Date | Well C | Well Class | |) | Facility Name | | Insp Status |
| 210856 | WELL | PR | 04/23/1998 | GW | | 045-06614 | | FEDERAL MV-7-4 | | PR |
| 286837 | WELL | PR | 04/01/2008 | GW | 045-12784 | | 84 | FEDERAL GM 431- | 4 | PR |
| 286838 | WELL | PR | 01/29/2009 | GW | | 045-1278 | 83 | FEDERAL GM 441- | 4 | PR |
| Follow up | General Comment: Follow up to 11/14/18 inspection 689702068 Corrective actions have been completed. | | | | | | | | | |

| <u>Location</u> | | | | | | | | | | |
|-----------------------------------|--|------------------|---------------------|--|--|-------|--------|-------|-----------------|---|
| Overall Good: 🔀 | | | | | | | | | | |
| Signs/Marker: | | | | | | | | | | |
| Туре | BATTERY | BATTERY | | | | | | | | |
| Comment: | Sign was re | ign was replaced | | | | | | | | |
| Corrective Action: | | | | | | | | Date: | | |
| Туре | WELLHEAD | /ELLHEAD | | | | | | | | |
| Comment: | | | | | | | | | | |
| Corrective Action: | | Date: | | | | | | | | |
| Туре | TANK LAB | ELS/PLACARI | os | | | | | | | |
| Comment: | Volumes we | ere painted on | tanks. | | | | | | | |
| Corrective Action: | | | | | | | | Date: | | |
| Emergency Contact N | lumber: | | | | | | | | | |
| | 970-285-93 | 377 | | | | | | | | |
| Corrective Action: | | | | | | | | Date: | | - |
| Good Housekeeping | <u></u> | | | | | | | | | |
| Туре | WEEDS | | | | | | | | | |
| Comment: | Weeds were | e adequately r | emoved. | | | | | | | |
| Corrective Action: | | | | | | | | Date: | | |
| Туре | UNUSED EQUIPMENT | | | | | | | | | |
| Comment: | Materials have been removed from location. | | | | | | | | | |
| Corrective Action: | | | | | | | Date: | | | |
| Overall Good: | | | | | | | | | | |
| Spills: | | | | | | | | | | |
| Туре | Area | | Volume | | | | | | | |
| In Containment: N | lo | | | | | | | | | |
| Comment: | | | | | | | | | | |
| Multilple Spills a | and Release | s? | | | | | | | | |
| Equipment: | | | | | | | | | corrective date | |
| Type: Deadman # & I | Marked | # | 3 | | | | | | | |
| Comment | Comment: Deadmen have been marked with tee post painted bright color | | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | | |
| Tanks and Berms: | | | | | | | | | | |
| Contents # Capacity | | | Type Tank ID SE GPS | | | | SE GPS | | | |
| CONDENSATE 1 300 BBLS STEEL AST , | | | | | | | | | | |
| Comment: | | | | | | | | | | |
| Corrective Action: | | | | | | | | Date: | | |
| <u>Paint</u> | | | | | | | | • | | |
| Condition Adequate | | | | | | | | | | |

Inspector Name: LONGWORTH, MIKE Other (Content) Other (Capacity) Other (Type) **Berms** Capacity Permeability (Wall) Maintenance Туре Permeability (Base) Metal Walls Sufficent Base Sufficient Adequate Adequate Comment: Corrective Action: Date: Capacity Tank ID SE GPS Contents Type PRODUCED WATER **200 BBLS** STEEL AST Comment: Corrective Action: Date: **Paint** Condition Adequate Other (Content) Other (Capacity) Other (Type) **Berms** Capacity Permeability (Wall) Permeability (Base) Maintenance Type Metal Adequate Walls Sufficent Base Sufficient Adequate Comment: Corrective Action: Date: Venting: Yes/No NO Comment: Corrective Action: Date: Flaring: Туре Comment: Corrective Action: Date:

| inspector Name. Levieworthi, Minte | | | | | | | | |
|------------------------------------|-------------------|------|-------------|--------------|-----------|----|---------------|----|
| | | | Inspected | d Facilities | | | | |
| Facility ID: 2108 | 56 Type: _ | WELL | API Number: | 045-06614 | Status: | PR | Insp. Status: | PR |
| | | | Produc | ing Well | | | | |
| Commen | t: Producing well | | | | | | | |
| Corrective Action | n: | | | | | | Date: | |
| | | | | | | | | |
| Facility ID: 2868 | 37 Type: _ | WELL | API Number: | 045-12784 | Status: _ | PR | Insp. Status: | PR |
| | | | Produc | ing Well | | | | |
| Commen | t: Producing well | | | | | | | |
| Corrective Action | 1: | | | | | | Date: | |
| | • | | | | | | | |
| Facility ID: 2868 | 38 Type: _ | WELL | API Number: | 045-12783 | Status: _ | PR | Insp. Status: | PR |
| | | | Produc | ing Well | | | | |
| Commen | t: Producing well | | | | | | | |
| Corrective Action | 1: | | | | | | Date: | |
| | | | | | | | | |

| mopodo Namo. Loneworth, with | | | | | | | | | | |
|------------------------------------|--------------------|----------------------------|--------------------------|--------------------|-----------------------------|---------|--|--|--|--|
| Reclamation - Storm Water - Pit | | | | | | | | | | |
| | | | | | | | | | | |
| Storm Water: | Storm Water: | | | | | | | | | |
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | | Chemical BMP Maintenance | Comment | | | | |
| | | | | | | | | | | |
| Comment: | Straw bails use | ed for storm water BMPs | have been repla | iced and repaired. | |] | | | | |
| Corrective Action: | | Date: | | | | | | | | |
| Pits: NO SURFACE INDICATION OF PIT | | | | | | | | | | |

Attached Documents

You can go to COGCC Images (https://cogcc.state.co.us/weblink/) and search by document number:

| Document Num | Description | URL |
|--------------|--------------------------------|--|
| 689702680 | Inspection 689702679 photo log | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4740926 |

Date Run: 2/20/2019 Doc [#689702679]