

Inspection Photos  
Location Name: SU 0680 3-9H16  
API: 05-057-06551



**Photo 1. Spills and staining.**



**Photo 2. Spills and staining.**

Inspection Photos  
Location Name: SU 0680 3-9H16  
API: 05-057-06551



**Photo 3. Spills and staining.**



**Photo 4. Spills and staining.**



Inspection Photos  
Location Name: SU 0680 3-9H16  
API: 05-057-06551



Photo 5. Spills and staining.



Photo 6. Spills and staining.

Inspection Photos  
Location Name: SU 0680 3-9H16  
API: 05-057-06551



Photo 7. Spills and staining.



Photo 8. Spills and staining.



Inspection Photos  
Location Name: SU 0680 3-9H16  
API: 05-057-06551



Photo 9. Spills and staining.



Photo 10. Spills and staining.

Inspection Photos  
Location Name: SU 0680 3-9H16  
API: 05-057-06551



**Photo 11. Spills and staining.**



**Photo 12. Spills and staining.**



Inspection Photos  
Location Name: SU 0680 3-9H16  
API: 05-057-06551



**Photo 13. Flare stack where fire occurred.**



**Photo 14. Burned tires on stack trailer from fire.**

Inspection Photos  
Location Name: SU 0680 3-9H16  
API: 05-057-06551



**Photo 15. No evidence of remaining fluids. Ice/snow melt with no visible sheen.**



**Photo 16. No evidence of remaining fluids. Ice/snow melt with no visible sheen.**