

Inspection Photo (s)
GMR 33-15D
API #05-045-10173
FIR Inspection # 689303410



Location Photo #1



Location Photo #2

Inspection Photo (s)
GMR 33-15D
API #05-045-10173
FIR Inspection # 689303410



Location Photo #3



Location Photo #4, Stained rock around the separator.

Inspection Photo (s)
GMR 33-15D
API #05-045-10173
FIR Inspection # 689303410



Location Photo #5, Stained rock at corner of separator.



Location Photo #6, Stained rock at corner of separator.

Inspection Photo (s)
GMR 33-15D
API #05-045-10173
FIR Inspection # 689303410



Location Photo #5, Stained rock under the heater of the separator.