

Inspection Photos

API: 05-025-06021

Operator: VAL ENERGY INC

Inspection Date: 3/11/2019

Inspection Photos



Photo 1. Facing southwest toward the location. There is sparse vegetation establishment.

Inspection Photos



Photo 2. Facing northwest toward the location. There is sparse vegetation establishment.

Inspection Photos



Photo 3. View of groundcover which is mostly bare soil.

Inspection Photos



Photo 4. Facing south toward the location. There is sparse vegetation establishment.

Inspection Photos



Photo 5. Facing west toward the undisturbed surrounding pasture.

Inspection Photos



Photo 6. Facing east toward the undisturbed surrounding pasture.