

# Inspection Photos

API: 05-025-06022

Operator: GRAND MESA OPERATING CO

Inspection Date: 3/11/2019

## Inspection Photos



**Photo 1.** Facing west along the access road. Culverts remain along the road.

## Inspection Photos



**Photo 2.** Facing south along the access road. The cattle guard remains.

## Inspection Photos



**Photo 3.** Facing southwest near the location. Decompaction of the soil begins at this point to the location.

## Inspection Photos



**Photo 4.** Facing toward the location. Decompaction has occurred at the location.

## Inspection Photos



**Photo 5.** Facing east at the location. Soil decompaction has occurred at the location. The soil has not been seeded and stabilized.

## Inspection Photos



**Photo 6.** Facing southwest at the location. This area appears to have been previously decompacted. Does not look like it has been seeded.