

Inspection Photos
Location Name: LARRY 14-26
API #: 05-071-07676
Insp. Doc. # 695100347



PHOTO 1: LOCATION



PHOTO 2: WELL SIGN/METER HOUSE

Inspection Photos

Location Name: LARRY 14-26

API #: 05-071-07676

Insp. Doc. # 695100347



PHOTO 3: IMPACTED SOIL ON EAST SIDE OF ENGINE SKID

PHOTO 4: IMPACTED SOIL AROUND WELLHEAD



Inspection Photos
Location Name: LARRY 14-26
API #: 05-071-07676
Insp. Doc. # 695100347




PHOTO 5: IMPACTED SOIL ON WEST SIDE OF ENGINE SKID

PHOTO 6: CALIBRATION REPORT IS PAST DUE