

Inspection Photos
Location Name: File 3R-32H-K268
Location ID: 434248



Pic 1, stained soil around wellhead from workover.



Pic2

Inspection Photos
Location Name: File 3R-32H-K268
Location ID: 434248



Pic 3



Pic 4

Inspection Photos
Location Name: File 3R-32H-K268
Location ID: 434248



Pic 5



Pic 6

Inspection Photos
Location Name: File 3R-32H-K268
Location ID: 434248



Pic 7



Pic 8

Inspection Photos
Location Name: File 3R-32H-K268
Location ID: 434248



Pic 9



Pic 10

Inspection Photos
Location Name: File 3R-32H-K268
Location ID: 434248



Pic 11



Pic 12

Inspection Photos
Location Name: File 3R-32H-K268
Location ID: 434248



Pic 13



Pic 14 Stained soil

Inspection Photos
Location Name: File 3R-32H-K268
Location ID: 434248



Pic 15



Pic 16

Inspection Photos
Location Name: File 3R-32H-K268
Location ID: 434248



Pic 17



Pic 18

Inspection Photos
Location Name: File 3R-32H-K268
Location ID: 434248



Pic 19



Pic 20

Inspection Photos
Location Name: File 3R-32H-K268
Location ID: 434248



Pic 21



Pic 22

Inspection Photos
Location Name: File 3R-32H-K268
Location ID: 434248



COLORADO OIL AND GAS CONSERVATION COMMISSION
40.09251, -105.03106, 4916.6ft, 228°
03/18/2019 15:03:41

Pic 23



COLORADO OIL AND GAS CONSERVATION COMMISSION
40.09255, -105.03099, 4908.2ft, 305°
03/18/2019 15:04:09

Pic 24 stained soil

Inspection Photos
Location Name: File 3R-32H-K268
Location ID: 434248



Pic 25. Temporary tank being used to collect crude oil.



Pic 26

Inspection Photos
Location Name: File 3R-32H-K268
Location ID: 434248



Pic 27



Pic 28

Inspection Photos
Location Name: File 3R-32H-K268
Location ID: 434248



Pic 29



Pic 30

Inspection Photos
Location Name: File 3R-32H-K268
Location ID: 434248



Pic 31



Pic 32

Inspection Photos
Location Name: File 3R-32H-K268
Location ID: 434248



Pic 33Unused equipment



Pic 34 Debris on location.