

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/26/2019

Submitted Date:

03/26/2019

Document Number:

675002079**FIELD INSPECTION FORM**
 Loc ID 334452 Inspector Name: Wentzel, Dougo On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 SEVENTEENTH STREET #1401City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:12 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	All Inspections
Peicka, Conor		conor.pesicka@state.co.us	All Inspections
Clark, Chris		cogccnotifications@laramie-energy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
278764	WELL	PR	05/03/2007	GW	077-08921	VEGA 34-24	PR
278765	WELL	PR	03/01/2014	GW	077-08920	VEGA 34-14	PR
278766	WELL	PR	02/01/2014	GW	077-08919	VEGA 34-13	PR
278775	WELL	PR	02/01/2014	GW	077-08923	VEGA 34-23	PR

General Comment:[This is a follow up inspection from Doc# 675001612 Dated 12/27/19](#)

Location				
Lease Road:				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	TANK LABELS/PLACARDS			
Comment:				
Corrective Action:				Date:
Type	BATTERY			
Comment:	Information on signs inaccurate at well heads and tank battery (entrance sign)			
Corrective Action:	Install sign to comply with Rule 210.b.			Date: 05/27/2019
Type	WELLHEAD			
Comment:	Corrective action of missing well head sign has been corrected			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	1-800-891-6191 911 and nearest access posted			
Corrective Action:				Date:
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	LOCATION			
Comment:				
Corrective Action:				Date:
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Equipment:				
Type: Pig Station	# 2			corrective date
Comment:				
Corrective Action:				Date:
Type: Bird Protectors	# 2			
Comment:				

Corrective Action:		Date:	
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS

METHANOL	1	<50 BBLS	STEEL AST		,	
Comment:						
Corrective Action:					Date:	
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:					Date:	
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
Flaring:						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities									
Facility ID:	278764	Type:	WELL	API Number:	077-08921	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Wells producing								
Corrective Action:						Date:			
Facility ID:	278765	Type:	WELL	API Number:	077-08920	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Wells producing								
Corrective Action:						Date:			
Facility ID:	278766	Type:	WELL	API Number:	077-08919	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Wells producing								
Corrective Action:						Date:			
Facility ID:	278775	Type:	WELL	API Number:	077-08923	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Wells producing								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						
		Gravel				
		Compaction				
Compaction						

Comment: Stormwater erosion appears to be controlled on the location at this time. Heavy snow still on location

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401986667	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4775152
675002080	Inspection 675002079 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4775149