

Inspection Photos
Location Name: GE 30-02
Location ID: 422359



Photo 1 GE 30-02



Photo 2 WH. Stained soil around well head. Packing on WH leaking at time of inspection.

Inspection Photos
Location Name: GE 30-02
Location ID: 422359



Photo 3 Stained soil around WH and packing leaking on well head.




Photo 4 WH. Stained soil around Hyd skid

Inspection Photos
Location Name: GE 30-02
Location ID: 422359




Photo 5 Unused equipment: 2" poly, 2" parts buried in dirt and exhaust hose.