



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type	Equipment	Volume	corrective date
Compressor	# 1		
Comment:	WELL IS BEING PRODUCED WITH A LIQUID RING COMPRESSOR (PRODUCED ON A VACUUM) WITH NO FORM 4 SUNDRY APPROVAL ON FILE.		
Corrective Action:	COMPLY WITH RULE 331.		Date: <u>05/09/2019</u>

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 271279 Type: WELL API Number: 071-07989 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402002174	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4789660">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4789660</a>
695100467	LOCATION PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4789651">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4789651</a>