

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil under and around PU motor exhaust pipe, plastic bottles of chemicals around PU motor		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e	Date:	10/12/2016
Type	OTHER		
Comment:	unused equipment fly wheel guard		
Corrective Action:	Comply with Rule 603.f .	Date:	10/12/2016

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	PUMP JACK		
Comment:	4' fabricated fencing		
Corrective Action:		Date:	

Equipment:

Type		#	corrective date
Type: Pump Jack		# 1	
Comment:			
Corrective Action:			Date:
Type: Prime Mover		# 1	
Comment:	Gas motor		
Corrective Action:			Date:
Type: Bradenhead		# 1	
Comment:			
Corrective Action:			Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		

Corrective Action:	Date:
--------------------	-------

--

Inspected Facilities

Facility ID: 203785 Type: WELL API Number: 001-09345 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Wednesday 5/7/19 at approximately 1100 I, Inspector Justin Medina conducted an on-site inspection at HSR-Lonnie 11-8 HRM Resources II LLC 001-09345 in Adams County Colorado. While there, I observed Shut in well This is a follow up inspection from document # 688400478 & 68550771 All CA from previous 2 inspections appear to have not been addressed, and are delinquent from 10/12/16 unused equipment fly wheel guard Comply with Rule 603.f . Stained soil under and around PU motor exhaust pipe, plastic bottles of chemicals around PU motor Properly treat or dispose of oily waste in accordance with 907.e A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	medinaj	05/07/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685100922	loc pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4817433