

Inspection Photos
Location Name: SGU-64S96W 23 SW SW Pad
Location ID: #335680
Inspection Date: May 30, 2019



Photo #1 – Well sign located at well head.



Photo #2 – View of tank battery from southeast.

Inspection Photos

Location Name: SGU-64S96W 23 SW SW Pad

Location ID: #335680

Inspection Date: May 30, 2019



Photo #3 – Unused, unmarked flowline riser located north of condensate AST.



Photo #4 – View of heated horizontal separator from SE. Note wood debris and flowline risers on south side of separator (visible under tarp).



Inspection Photos

Location Name: SGU-64S96W 23 SW SW Pad

Location ID: #335680

Inspection Date: May 30, 2019



Photo #5 – Unused 2" flowline risers, wood debris, and chemical storage tanks located east of separator.



Photo #6 – Trash on location (can north of chemical storage tanks).



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: SGU-64S96W 23 SW SW Pad

Location ID: #335680

Inspection Date: May 30, 2019



Photo #7 – Trash on location (filter sock on north side of pad).



Photo #8 – Assorted trash on north side of location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: SGU-64S96W 23 SW SW Pad

Location ID: #335680

Inspection Date: May 30, 2019



Photo #9 – Cut slope on SE side of pad. Operator has submitted eForm 04 Sundry (doc #402030679) for beneficial reuse of cuttings to reclaim this area.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources