

Inspection Photos
Operator Name: Caerus
Location ID: 335806



Spill location, 2" Dump line



2" Dump line, Repairs made, target tee removed

Inspection Photos
Operator Name: Caerus
Location ID: 335806



Unmarked riser



Process piping unprotected

Inspection Photos
Operator Name: Caerus
Location ID: 335806



Unmarked Flowline



Unused flowline