

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/20/2019

Submitted Date:

06/24/2019

Document Number:

696300270**FIELD INSPECTION FORM**Loc ID 419394 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10459Name of Operator: EXTRACTION OIL & GAS INCAddress: 370 17TH STREET SUITE 5300City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCInspections@extracti onog.com	All Inspectors
,		dnr_cogccenforcement@state .co.us	
Kraich, Adam		adam.kraich@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
419401	WELL	SI	05/01/2018	OW	123-32232	MORO FARMS 34-29	SI
419409	WELL	SI	11/01/2017	OW	123-32236	MORO FARMS CSE-29	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate (X2)		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Good Housekeeping:		
Type	WEEDS	
Comment:	Weeds at Wellheads, see photo #2	
Corrective Action:	Comply with 603.f	Date: 05/10/2019

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Fencing/:		
Type	WELLHEAD	
Comment:	Chainlink (X2)	
Corrective Action:		Date:

Equipment:			corrective date
Type: Bradenhead	# 2		
Comment:	Appears to plumbed to surface		
Corrective Action:		Date:	
Type: Plunger Lift	# 2		
Comment:			
Corrective Action:		Date:	

Venting:		
Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:		
Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 419401 Type: WELL API Number: 123-32232 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: SI

Corrective Action: _____ Date: _____

Facility ID: 419409 Type: WELL API Number: 123-32236 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: SI

Corrective Action: _____ Date: _____

COGCC Comments

Comment

COGCC Inspection Report Summary
 On Thursday, 06.20.2019 at approximately 12:30 PM, I, Inspector Erica Petrie, conducted a Field Inspection at Extraction Oil and Gas, Moro Farms - 34-29 & CSE-29 Wellheads, Location #419394 in Weld, Colorado.
 While there, I observed Production, wells shut-in at the time of inspection.
 During this inspection the following possible compliance issues were observed:
 Debris/Weeds at wellheads from previous Inspection Document ID 679600657 have not been removed. Comply with Rule 603.f, See photos. Corrective Action date of 05.10.2019

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.
 This is a summary of inspection report.

User

petrie

Date

06/24/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696300276	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4858576