

Inspection Photos

API: 05-073-06312

Operator: NIGHTHAWK PRODUCTION

Inspection Date: 6/24/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06312 | Date: 6/24/2019

Inspection Photos



Photo 1. Facing northwest toward the location. Location is fenced.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06312 | Date: 6/24/2019

Inspection Photos



Photo 2. There is List B noxious weeds (Russian knapweed) at the southeast side of the location. Also, Chicory was observed in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06312 | Date: 6/24/2019

Inspection Photos



Photo 3. Facing northwest at the northern portion of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06312 | Date: 6/24/2019

Inspection Photos



Photo 4. There is a bare area and undesirable weeds at the northern portion of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06312 | Date: 6/24/2019

Inspection Photos



Photo 5. Northwest side of the location is bare of vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06312 | Date: 6/24/2019

Inspection Photos



Photo 6. There is List B noxious weeds (Russian knapweed) at the west side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06312 | Date: 6/24/2019

Inspection Photos



Photo 7. Facing east at the southern side of the location. Vegetation is well established in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06312 | Date: 6/24/2019