

# Inspection Photos

API: 05-071-06218

Operator: MERIDIAN OIL INC

Inspection Date: 4/18/2019

## Inspection Photos



**Photo 1.** Facing west along the main road toward the location fill slope.

## Inspection Photos



**Photo 2.** From the main road facing south toward the location.

## Inspection Photos



**Photo 3.** Facing southwest at the location.

## Inspection Photos



**Photo 4.** There are four guy-line anchors that remain at the location.

## Inspection Photos



**Photo 5.** Facing toward the cut slope.

## Inspection Photos



**Photo 6.** There is an erosion channel at the southwest cutslope.

## Inspection Photos



**Photo 7.** The unstable cut slope is estimated to be 100 ft. high.

## Inspection Photos



**Photo 8.** Facing toward the cut slope.

## Inspection Photos



**Photo 9.** Facing south toward the cut slope.