

# Inspection Photos

API: 05-071-06218

Operator: MERIDIAN OIL INC

Inspection Date: 7/1/2019

## Inspection Photos



**Photo 1.** From the main road facing south toward the location. Unstable cut slope remains. Location not recontoured.



## Inspection Photos



**Photo 2.** There is a pit at the west side of the location.



## Inspection Photos



**Photo 3.** Facing southeast at the location.



## Inspection Photos



**Photo 4.** There is a hole with steel grate at center of location. Did not see conductor or casing in the hole.



## Inspection Photos



**Photo 5.** There are numerous noxious weeds throughout the site. Shown in photo is Common mullein and Field bindweed.



## Inspection Photos



**Photo 6.** Facing toward the cutslope. The unstable cut slope is estimated to be 100 ft. high.



## Inspection Photos



**Photo 7.** There are four guyline anchors that remain at the location.