



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

OTHER

Comment:

PHOTO 3: IMPACTED SOIL UNDER PUMPJACK PRIME MOVER.  
PHOTO 4: IMPACTED SOIL UNDER PUMPJACK GEAR BOX.

Corrective Action:

Remove and dispose impacted material in approved manner, service and maintain equipment and self inspect to prevent recurrence of conditions per 1002.f(2) and 907. CA DATE 8/8/19.

Date: 08/08/2019

Overall Good:

**Spills:**

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

corrective date

Type: Bradenhead

# 1

Comment:

PLUMBED TO SURFACE

Corrective Action:

Date:

**Venting:**

Yes/No

NO

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**Facility ID: 217887 Type: WELL API Number: 071-06666 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402099496	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4871473">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4871473</a>
695100979	LOCATION PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4871467">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4871467</a>