

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/15/2019

Submitted Date:

07/15/2019

Document Number:

687905157

FIELD INSPECTION FORM

Loc ID 325648 Inspector Name: Stewart, Joseph On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 96735
Name of Operator: WILLIFORD RESOURCES, L.L.C.
Address: 6506 S LEWIS AVE STE 102
City: TULSA State: OK Zip: 74136

Findings:

- 11 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Callahan, Linda	(918) 712-8828	lcallahan3@swbell.net	e-mail receipient
Labowskie, Steve		steve.labowskie@state.co.us	
Stevens, Glenn	(970) 749-0192	glennstevens@centurylink.net	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215165	WELL	PR	06/01/2017	GW	067-06770	SPRING HOLLOW MAC 3	PR

General Comment:

[Site inspection with photos at the end of this report.](#)

Location			
Lease Road:			
Type	Access		
comment:	Two-track dirt road.		
Corrective ActionL		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign posted at pumpjack.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Contact information and 911 posted on sign.		Date:
Corrective Action:			
Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds around pumpjack.		
Corrective Action:	Control weeds per Rule 603.f.		Date: 07/25/2019
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Ancillary equipment	# 1		corrective date
Comment:	Wellhead has stained soil around it.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.		Date: 08/15/2019
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Engine has oil leak creating stained soil below it.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.		Date: 08/15/2019
Type: Flow Line	# 2		
Comment:	1-2" flowline from wellhead to centralized crude oil tank battery. 1-1" flowline from wellhead to pumpjack engine fuel gas.		
Corrective Action:		Date:	
Venting:			
Yes/No			

Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 215165 Type: WELL API Number: 067-06770 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing.](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Ditches	Pass	Culverts	Pass			
				Material Handling And Spill Prevention	Pass	Spill prevention for 55 gallon drum.

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402109543	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879097
687905173	Stained soil around wellhead.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879076
687905174	Leaking engine and stained soil.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879077
687905175	Weeds around equipment.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879078