

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/26/2019

Submitted Date:

07/26/2019

Document Number:

679704897

**FIELD INSPECTION FORM**

Loc ID 311838 Inspector Name: Moran, Rick On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 100264  
Name of Operator: XTO ENERGY INC  
Address: 110 W 7TH STREET  
City: FORTH WORTH State: TX Zip: 76102

**Findings:**

- 7 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
Reid, Van		van_reid@xtoenergy.com	
Dooling, Jessica	970-769-6048	Jessica_Dooling@xtoenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
261058	WELL	PR	06/01/2017	GW	103-10191	PICEANCE CREEK UNIT T33X-29G	PR

**General Comment:**

[COGCC Inspection Report Summary.](#)

On 7-26-2019 at approximately 15:00, inspector Rick Moran, conducted a routine inspection at XTO Energy well Piceance Creek Unit T33X-29G in Rio Blanco county.

During this inspection the following compliance issues were observed:

- 1) "911" on battery sign. Photo 2. Complete by 8-26-2019.
- 2) Unmarked deadman. Photo 3. Complete by 8-16-2019.
- 3) Trash. Photo 4. Complete by 8-26-2019.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679704897.

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Missing "911" on battery sign.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	08/26/2019
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911		
Corrective Action:		Date:	_____

**Good Housekeeping:**

Type	TRASH		
Comment:	Electric conduit on edge of location east of the 3 wells.		
Corrective Action:	Comply with Rule 603.f .	Date:	08/26/2019

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

**Fencing/:**

Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

**Equipment:**

Type: Deadman # & Marked	# 5		corrective date
Comment:	Two unmarked deadmen.		
Corrective Action:	Install proper guy line markers per Rule 1003.a	Date:	08/16/2019
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			

Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	400 BBLs	STEEL AST		39.943100,-108.194600
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	1000 BBLs	STEEL AST		39.943100,-108.194600
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	750 bbl	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 261058 Type: WELL API Number: 103-10191 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing well on plunger lift.](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No apparent significant soil migration, erosion, or soil movement on location.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679704898	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4892739">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4892739</a>