

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/18/2019

Submitted Date:

07/20/2019

Document Number:

694500115**FIELD INSPECTION FORM**Loc ID 313122 Inspector Name: NEIDEL, KRIS On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10407Name of Operator: ANTLER ENERGY LLCAddress: PO BOX 104City: BAGGS State: WY Zip: 82321**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
		antlerenergy@yahoo.com	
Clay, Evans		clay@antler-energy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
100405	PIT				-	POWDER WASH COMPRESSOR	EI
100409	PIT				-	PTASYNSKI 2 TANK BATTERY	EI
116633	PIT	AC			-	USA CLARK MILLISON	EI
223599	WELL	PR	09/09/1966	GW	081-07006	USA-CLARK - MILLISON 1	EI

**General Comment:**

On 6/18/2019, COGCC staff, Kris Neidel and Alex Fischer inspected the USA Clark Millison #1 and adjacent facility's; old compressor buildings, equipment storage, land treatment area, flow line risers, etc. COGCC database shows three pits associated with this well, facility 100405, 100409, 116633, please provide status update on these three pits (location, history of use, current status, etc). No pits were observed in the area of the millison well. There is a land treatment area near the Millison #1, it appears that it is part of project number 7362. By 8/5/2019 submit an supplemental eForm 27 project update to this REM project. Trash and debris was observed in old compressor stations and around location. A deceased bird was observed in the secondary containment of a storage tank with the id "ATF", the operator should ensure that stored equipment does not pose a threat to wildlife. Antler Energy should ensure that and appropriate notification has been given to Colorado Parks and Wildlife for the deceased bird. There are multiple piperisers and flowlines on location, the operator should ensure that all flowlines are compliant with COGCC rule 1101. Stored tanks have evidence of leaking fluid. See this document for Corrective Actions. Photos attached. Operator should ensure actions required from previous inspections are completed, this inspection address specific Environmental items are documented here and does not necessary address previous required action required. Well was SI at time of inspection.

**Location**Overall Good: ☐

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Sign or label not posted or information inaccurate on tanks or containers. Not all tanks contain complete, accurate labels.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	01/15/2016

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Multiple areas on location contain equipment that does not appear to be in use including but not limited to: tubing, tanks, separators, valves, wellhead and pump jack parts, chemical totes, tarping.		
Corrective Action:	Comply with Rule 603.f .	Date:	02/04/2014
Type	STORAGE OF SUPL		
Comment:	Multiple areas on location contain stored, aging supplies including but not limited to: tubing, tanks, separators, valves, wellhead and pump jack parts, chemical totes, tarping.		
Corrective Action:	Comply with Rule 603.f .	Date:	02/04/2014

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	
PW/CO	Tank	<= 1 bbl	
Comment:	Drips around stored, out of service tanks.		
Corrective Action:	Prevent all equipment from leaking, remove contaminated soils.		Date: 08/02/2019

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: <u>100405</u>	Type: <u>PIT</u>	API Number: <u>-</u>	Status: <u></u>	Insp. Status: <u>EI</u>
Facility ID: <u>100409</u>	Type: <u>PIT</u>	API Number: <u>-</u>	Status: <u></u>	Insp. Status: <u>EI</u>
Facility ID: <u>116633</u>	Type: <u>PIT</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>EI</u>
Facility ID: <u>223599</u>	Type: <u>WELL</u>	API Number: <u>081-07006</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402116134	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4885244">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4885244</a>
694500123	photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4885242">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4885242</a>