

Inspection Photos

API: 05-055-06316

Operator: OXY USA INC

Inspection Date: 8/1/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-055-06316 | Date: 8/1/2019

Inspection Photos



Photo 1. Facing east along the main access road. There are some noxious weeds along the road that are wilting.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06316 | Date: 8/1/2019

Inspection Photos



Photo 2. The road was graded and rock wattle damns were repaired. The sediment trap was cleaned out and erosion repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06316 | Date: 8/1/2019

Inspection Photos



Photo 3. The well sign has fallen over. This has not been repaired since previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06316 | Date: 8/1/2019

Inspection Photos



Photo 6. Facing northeast along the hill side at the location. There are numerous noxious weeds (Canada thistle) in this area that have not been controlled since previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06316 | Date: 8/1/2019