FORM INSP Rev

X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/29/2019
Submitted Date:

09/09/2019

Document Number: 693900740

## FIELD INSPECTION FORM

Loc ID 326452	•			On-Site Inspection  2A Doc Num:		Status Summary:  THIS IS A FOLLOW UP INSPECTION		
						FOLLOW UP INSPECTION REQUIRED		
Operator In	nformation:							
OGCC Ope	erator Number:	10133				NO FOLLOW	UP INSPECTION	I KEQUIKED
Name of Op	perator: HILCORF	PENERGY	COMPANY			Findings:		
						6 Number of Comments		
Address: F	P O BOX 61229					2 Number of	of Corrective Actio	ns
City:	HOUSTON	State:	e: TX Zip: 77208			Corrective Action Response Requested		
Contact Int	form of law.					PREVIOUS II	CTIVE ACTION(S NSPECTIONS TH ESSED ARE STII	ÁT HAVE NOT
Contact Inf		Dha		[F:1]		0		
Contact Name Phone				Email		Comment		
Ray, Mandy (505) 59			599-4083	mray@hilcorp	o.com	All Inspections		
Shorty, Priscilla				pshorty@hilco	orp.com	All SW Inspections		
Inspected I	Facilities:							
Facility ID	Туре	Status	Status Date	Well Class	API Num	Facility N	lame	Insp Status
216522	WELL	PR	12/01/2017	GW	067-0812	8 ARGENT	ΓA 33-10 3-1	RI
General Co This is an	omment: interim reclamatio	on and storr	nwater inspect	ion.				

Inspector Name: ROY, CATHERINE **Location** Overall Good: **Emergency Contact Number:** Comment: Corrective Action: Date: **Good Housekeeping: WEEDS** Туре Comment: Dense kochia weeds up to 2.5 feet tall identified around the wellhead and well facilities. Corrective Action: Comply with rule 603f Date: 09/23/2019 Overall Good: Spills: Туре Area Volume In Containment: No Comment: Multilple Spills and Releases? Venting: Yes/No Comment: Corrective Action: Date: Flaring: Туре Comment: Corrective Action: Date:

				Inspecte	d Facilities				
acility ID:	216522	Type: _	WELL	API Number:	067-08128	Status:	PR	Insp. Status:	RI

Reclamation - Storm Water - Pit						
Interim Reclamation	<u>1:</u>					
Date Interim Reclamation Started: Date Interim Reclamation Completed:						
Land Use:	Land Use:					
Comment:						
1002 SITE PREPAR	ATION AND STABILIZATION					
1002a. FENCIN	G					
Comment						
Corrective Action		Date				
1002b. SOIL RE	MOVAL AND					
Comment						
Corrective Action		Date				
1002c. PROTEC	CTION OF SOILS					
Comment						
Corrective Action		Date				
1002E. SURFAC	CE DISTRURBANCE MINIMIZATION					
Comment						
Corrective Action		Date				
1003a. Waste a	nd Debris removed?					
Comment						
Corrective Action		Date				
Unused	or unneeded equipment onsite? Pass					
Comment [						
Corrective Action		Date				
Pit, cellars, rat holes and other bores closed?						
Comment						
Corrective Action		Date				
Guy line	anchors marked?					
Comment						
Corrective Action		Date				

Inspector Name: ROY, CATHERINE 1003b. Area no longer in use? Production areas stabilized? 1003c. Compacted areas have been cross ripped? Subsidence over on drill pit? 1003d. Drilling pit closed? Cuttings management: 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Production areas have been stabilized? Segregated soils have been replaced? RESTORATION AND REVEGETATION Cropland Top soil replaced Recontoured Perennial forage re-established Non-Cropland Recontoured Top soil replaced 80% Revegetation In 1003e. INTERIM VEGETATION TRANSECT TRANSECT RESULTS OF DISTURBED AREA% TRANSECT RESULTS OF REFERENCE AREA% TOTAL % OF DESIRABLE VEGETATION COVER VEGETATIVE COVER 1003 f. Weeds Noxious weeds? Comment Noxious weeds appear to be controlled at this time. Revegetation is progressing within the majority of the interim reclamation areas and along the access road, except where erosion is occurring as noted in stormwater erosion below. Corrective Action Overall Interim Reclamation Fail Final Reclamation/ Abandoned Location: Date Final Reclamation Started: Date Final Reclamation Completed: Final Land Use: Reminder: Comment: Well plugged Pit mouse/rat holes, cellars backfilled Debris removed No disturbance /Location never built Contoured \_\_\_\_ Culverts removed \_\_\_\_ Access Roads Regraded \_\_\_\_\_ Gravel removed Location and associated production facilities reclaimed Locations, facilities, roads, recontoured Compaction alleviation Dust and erosion control Cropland: perennial forage Non cropland: Revegetated 80% Weeds present Subsidence 1004.d. FINAL VEGETATION TRANSECT TRANSECT RESULTS OF DISTURBED AREA% TRANSECT RESULTS OF REFERENCE AREA% TOTAL % OF DESIRABLE VEGETATION COVER VEGETATIVE COVER Comment: Corrective Action: Date

Overall Final Reclamation		Well R	ocation			
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment:	Erosional tunneling is occurring within the southeastern project area. Erosional rilling and channeling is occurring at the well pad entrance. Erosional downcutting is occurring along the shared portion of the access road around a culvert. This is compromising the stability of the road.					
Corrective Action:	Stormwater er need to be sel such as those	Date: 09/27/2019				

## **Attached Documents**

You can go to COGCC Images (https://cogcc.state.co.us/weblink/) and search by document number:

Document Num	Description	URL		
402170508	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4932067		
693900747	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4932064		