

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/25/2019

Submitted Date:

09/25/2019

Document Number:

687905549

**FIELD INSPECTION FORM**

Loc ID 326096 Inspector Name: Stewart, Joseph On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10000  
Name of Operator: BP AMERICA PRODUCTION COMPANY  
Address: 1199 MAIN AVENUE SUITE 101  
City: DURANGO State: CO Zip: 81301

**Findings:**

- 18 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	<a href="#">COGCC</a>
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	<a href="#">SW Inspection Reports</a>
Inspections, All		SanJuanCOGCC@bp.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215860	WELL	PR	08/13/2015	GW	067-07465	CYRUS JOHNSON A 1	PR

**General Comment:**

[Site inspection and equipment inventory with photos at the end of this report.](#)

<b>Location</b>			
<b>Lease Road:</b>			
Type	Access		
comment:	Gravel access road through SUIT land.		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Labels posted on tanks.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Sign posted at entrance to location.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Contact information posted on signs.		
Corrective Action:		Date:	_____
<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment spools that have been disconnected from compressor suction and discharge and piping blinded. See photo#		
Corrective Action:	Remove unused equipment per Rule 603.f.	Date:	10/25/2019
Type	UNUSED EQUIPMENT		
Comment:	Compressor and associated equipment and flowlines to include: knockout scrubber, exhaust manifold, muffler, and PBV blowdown drum are all disconnected from process and blinded and are not in use and are unused equipment. Compressor is currently bypassed with LOTO on suction/discharge valves. See photo#		
Corrective Action:	Remove unused equipment or put back in service per Rule 603.f.	Date:	10/25/2019
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:	_____		
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
Type: Deadman # & Marked	# 6		corrective date
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		

Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 10		
Comment:	1-4" steel flowline from wellhead to separator inlet. 1-6" flowline from separator outlet to compressor suction. 1-2" flowline from separator dump valve to produced water tank. 1-2" flowline from compressor scrubber dump valve to produced water tank. 1-2" flowline from compressor knockout pot to produced water tank. 1-1" flowline from separator to heated tank fuel gas. 1-2" flowline from produced water tank to water transfer pump. 1-2" flowline from water transfer pump to offsite gathering system. 1-6" flowline from compressor discharge to meter house. 1-6" flowline from meter house to offsite dogleg.		
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:	On heated tank (1) and on separator stack (1)		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Produced water transfer pump in metal building.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	PVC bradenhead access.		
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead with valve assembly and block valves.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	HEATED STEEL AST		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS

PRODUCED WATER	1	<50 BBLs	PBV STEEL		
Comment:					
Corrective Action:					Date:
<b>Paint</b>					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
<b>Venting:</b>					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
<b>Flaring:</b>					
Type					
Comment:					
Corrective Action:					Date:

**Inspected Facilities**

Facility ID: 215860 Type: WELL API Number: 067-07465 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing.](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gradient Terraces	Pass	Ditches	Pass			
Ditches	Pass	Culverts	Pass			
				Material Handling And Spill Prevention	Pass	Spill prevention for antifreeze tank.
Compaction	Pass	Compaction	Pass			
				Material Handling And Spill Prevention	Pass	Spill prevention for lube oil tank.
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402189422	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4947442">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4947442</a>
687905560	Cyrus Johnson A1 inspection photos.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4947432">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4947432</a>