

Inspection Photos

Operator: Kinder Morgan
Location/API #: 083-06730
Date: 10-3-2019



Photo 1. View of the project area from the northeastern edge facing center.



Photo 2. View of a portion of the topsoil stockpile and grader equipment operating at the time of the inspection.



Photo 3. View of the southern edge of the project area from the southeastern corner facing westward. Ditch and berm in place. Loose soil on top of berm is not stabilized. Reference area on left side of photo is comprised of dryland crop field that is not planted at this time.



Photo 4. View of the northern portion of the project area facing westward. Ditch and berm are in place. However, loose soil on berms and in ditches is not stabilized and additional stabilization is needed.



Photo 5. View of access road facing eastward to ward Montezuma County Road. Access is graveled and vegetation is becoming established on roadsides.