

**Inspection Photos**  
**Location Name: Meyers 19-11HA**  
**Location ID: 441283**



**Photo 1. Overview of location taken at entrance facing southwest.**



**Photo 2. Stained soil at pump jack exhaust.**