

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/16/2019

Submitted Date:

10/16/2019

Document Number:

694900589**FIELD INSPECTION FORM**

Loc ID 334830	Inspector Name: Ramsey, Scott	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: <u>10456</u> Name of Operator: <u>CAERUS PICEANCE LLC</u> Address: <u>1001 17TH STREET #1600</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				Findings: 11 Number of Comments 2 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211428	WELL	PR	09/22/1997	GW	045-07188	GRAHAM 32-12	PR
265591	WELL	PR	10/09/2008	GW	045-09029	GRAHAM 32-12D (L32)	PR
265592	WELL	SI	08/01/2018	GW	045-09030	COUEY 32-5D (L32)	SI
265593	WELL	PR	06/18/2003	GW	045-09028	GRAHAM 32-12B (L32)	PR
265594	WELL	PR	06/16/2003	GW	045-09031	SHIDELER 32-11D (L32)	PR
265595	WELL	PR	06/15/2003	GW	045-09032	COUEY 31-9D (L32)	PR

General Comment:**COGCC Inspection Report Summary**

On Wednesday 10/16/19 at approximately 1:00 PM, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus L32 Pad, at Location # 334830 in Garfield County, Colorado.

While there, I observed normal production operations.

During this inspection the following possible compliance issues were observed:

Debris in tank containment.

Still has Encana label on tank along with Caerus.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Encana label is still on tank along with Caerus		
Corrective Action:	Remove label see photo	Date:	11/18/2019

Emergency Contact Number:		
Comment:	911	
Corrective Action:		Date: _____

Good Housekeeping:			
Type	DEBRIS		
Comment:	debris in tank containment		
Corrective Action:	remove debris see photos	Date:	11/18/2019

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:	livestock fence		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	livestock fence		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Vertical Heated Separator	# 5		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			

Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 6		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	300 BBLS	HEATED STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:	Date:		

Flaring:

Type			
Comment:			
Corrective Action:	Date:		

Inspected FacilitiesFacility ID: 211428 Type: WELL API Number: 045-07188 Status: PR Insp. Status: PR**Producing Well**Comment: producing

Corrective Action:

Date:

Facility ID: 265591 Type: WELL API Number: 045-09029 Status: PR Insp. Status: PR**Producing Well**Comment: producing

Corrective Action:

Date:

Facility ID: 265592 Type: WELL API Number: 045-09030 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: _____

Corrective Action: _____

Date: _____

Facility ID: 265593 Type: WELL API Number: 045-09028 Status: PR Insp. Status: PR**Producing Well**Comment: producing

Corrective Action:

Date:

Facility ID: 265594 Type: WELL API Number: 045-09031 Status: PR Insp. Status: PR**Producing Well**Comment: producing

Corrective Action:

Date:

Facility ID: 265595 Type: WELL API Number: 045-09032 Status: PR Insp. Status: PR**Producing Well**Comment: producing

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						
Compaction		Gravel				
Berms		Compaction				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402212363	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4965106
694900594	694900589	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4965101