

Inspection Photos


Location Name: Facility #8 Consolidated Gas Line

Location ID: 452596



COGCC Environmental Inspection
40.04387, -104.85785, 4900.3ft, 310°
10/24/2019 02:30:15 PM

**Photo 1 – Foreground: Unmarked valve culvert
Background: Anadarko Norden Receiver**



COGCC Environmental Inspection
40.04393, -104.85782, 4899.1ft, 283°
10/24/2019 02:30:04 PM

Photo 2 – Inside culvert

Inspection Photos

Location Name: Facility #8 Consolidated Gas Line

Location ID: 452596



Photo 3 – Unmarked culvert. Excavation was backfilled imported material; surface appears to be road base or a similar material.



Photo 4 – Fill material adjacent to culvert.

Inspection Photos

Location Name: Facility #8 Consolidated Gas Line

Location ID: 452596



Photo 5 – Looking west; area of excavation related to Remediation #10757. Gravel is from the pigging station pad.



Photo 6 – Looking west; area of excavation related to Remediation #10757.

Inspection Photos

Location Name: Facility #8 Consolidated Gas Line

Location ID: 452596



Photo 7 – Fill material



Photo 6 – Native soil