

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/08/2019

Submitted Date:

11/08/2019

Document Number:

699300545

FIELD INSPECTION FORM

Loc ID 336295 Inspector Name: Revas, Robbie On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 11 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Pesika, Conor		conor.pesicka@state.co.us	
,		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241291	WELL	SI	06/01/2019	OW	123-09079	PERRIN-MAHONEY 2	SI

General Comment:

(This area is currently blank for general comments.)

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:		Date:	

Good Housekeeping:

Type	OTHER		
Comment:	Possible leak on flow line valve coming from WH.		
Corrective Action:	Rule 605.d: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition.	Date:	11/23/2019
Type	OTHER		
Comment:	Stained soil by flow line valve from WH		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e	Date:	11/23/2019

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	barb wire		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	steel pipe		
Corrective Action:		Date:	

Equipment:

Type	#	Comment	Corrective Action	Date	corrective date
Pump Jack					
Bradenhead	# 1	appears plumbed to surface			
Prime Mover	# 1	electric motor			

Type: Ancillary equipment	# 1		
Comment:	electric panel		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 241291 Type: WELL API Number: 123-09079 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Friday 11/8/2019 at approximately 1300 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at KP Kaufman:</p> <p style="text-align: center;">Perrin-Mahoney #2 at API #05-123-09079 in Weld County Colorado.</p> <p>While there, I observed a Shut in wellsite. Routine inspection. During this inspection the following compliance issue was observed: Rule 907.e: Stained soil by Flow line valve coming off WH. CA date 11/23/2019 see photos 3 & 4. Rule 605.d: COGCC Inspection Report Summary On Friday 11/8/2019 at approximately 1330 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at KP Kaufman:</p> <p style="text-align: center;">Perrin-Mahoney #2 at API #05-123-09079 in Weld County Colorado.</p> <p>While there, I observed a Shut in wellsite. Routine inspection. During this inspection the following compliance issue was observed: Rule 907.e: Stained soil by Flow line valve coming off WH. CA date 11/23/2019 see photos 3 & 4. Rule 605.d Mechanical issue: Possible leak on flow line valve coming from WH. CA date 11/23/2019 see photo 4. Location is dry, weather is clear. A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. Continuing education COGCC Inspection Report Summary. This is a summary of inspection report.</p> <p>Location is dry, weather is clear. A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. Continuing education COGCC Inspection Report Summary. This is a summary of inspection report.</p>	revasr	11/08/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699300546	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4984626