Inspection Photos

Location Name: Cuykendall-Lauck #2

Location ID: 317921





Photo1 WH sign Photo2 WH



Inspection Photos Location Name: Cuykendall-Lauck #2 Location ID: 317921



40.14008, -104.48279, 4818.8ft, 107°

11/25/2019 13:03:07




Photo3 Access rd. appears to have weeds cut and removed

Photo4 unguarded belts on PU



Inspection Photos Location Name: Cuykendall-Lauck #2

Location ID: 317921





Photo5 Stained soil under PU pulley

Photo6 ECD and separator house



Inspection Photos Location Name: Cuykendall-Lauck #2

Location ID: 317921





Photo7 Produced water tank has been marked with volume

Photo8 TB sign



Inspection Photos Location Name: Cuykendall-Lauck #2 Location ID: 317921





Photo 9 TB Photo 10 Gas meter run



Inspection Photos Location Name: Cuykendall-Lauck #2 Location ID: 317921





Photo11 Stained soil under Crude oil tank valve appears to have been removed

Photo12 Stained soil under Crude oil tank valve appears to have been removed

