

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/11/2019

Submitted Date:

12/13/2019

Document Number:

692401679**FIELD INSPECTION FORM**Loc ID 324339 Inspector Name: Colby, Lou On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 SEVENTEENTH STREET #1401City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		cogccnotifications@laramie-energy.com	All inspections
Longworth, Mike		michael.longworth@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
280073	WELL	PR	09/07/2006	GW	045-11172	OXY FEDERAL 797-08-19D	RI

General Comment:

This is a Reclamation Stormwater Inspection, prompted by notice of condition of Location access road diverting off Conn Creek Road. Access road is so degraded/ rutted/sloppy to make site appear inaccessible without further degradation of road and tracking onto Conn Creek Rd. Inspector did not attempt to access Location because of risk; therefore, this Insp only addresses this one Stormwater/Access issue. Operator was contacted and informed of issue and need for immediate Action.

Insp Doc#689703246 Dated 6/26/19 had CA addressing road conditions, which were resolved by Follow Up Insp 7/19/19; however this Inspection may be indicating that major road improvement work is indicated.

Inspected Facilities									
Facility ID:	280073	Type:	WELL	API Number:	045-11172	Status:	PR	Insp. Status:	RI

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Severe degradation of access road and vehicle tracking is occurring.

Corrective Action: Install sufficient/effective BMPs in accordance with, and monitoring per Good Engineering Practices per Rule 1002.f ASAP: Operator was contacted and informed of issue and need for immediate Action.

Maintain vehicle tracking BMPs on the oil and gas location to comply with rule 1002.f.(2)F.

Date: 12/16/2019

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
692401680	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5012536