

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/11/2019

Submitted Date:

12/16/2019

Document Number:

697600665**FIELD INSPECTION FORM**Loc ID 317729 Inspector Name: GINTAUTAS, PETER On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Lara-Mesa, Susana	303-825-4822	cogcc@kpk.com	Eng'g Project Mgr

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
469782	TANK BATTERY	AC	12/11/2019		-	J A Kunzman 1,2,4 & 43-6 battery	EI

General Comment:

production facilities not co-located with wells served by the battery
 Battery only inspected in this report
 battery signs indicate following wells flow to this battery
 123-07666
 123-09296
 123-09719
 123-16116

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: [contact information on battery sign](#)

Corrective Action: Date:

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: [no spills observed at surface during inspection](#)☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Other	# 1		
Comment:	manifold system for flowlines		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	secondary pump		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLS	CONCRETE SUMP/VAULT		40.160770,-104.802838
Comment:	located in separate berm than crude tank and to north of crude tank				
Corrective Action:				Date:	

Paint

Condition	
Other (Content)	
Other (Capacity)	50bbbs
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent		Adequate	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		40.160041,-104.802530
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate			Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 469782 Type: TANK API Number: - Status: AC Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697600666	crude tank and battery sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5013686
697600667	prodced water vault	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5013687
697600668	manifold and gas meter run	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5013688
697600669	secondary pump	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5013689