

Well Name: Ford Olson Unit 1 **API #** 05-067-05464

Inspection Number: 693900214

Corrective Action: Storm water controls need maintenance or replaced, additional erosion control measures need to be taken along eastern cut slope and drainage ditches.

Correction Action Due: 5/20/2019

Action Completed: 5/24/2019 Note: Corrective action was delayed due to in-climate weather.

Action Taken: Cleaned out and added waddles to eastern cut slope, cleaned out and installed rock check dams to drainage ditches.

