

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/17/2019

Submitted Date:

01/10/2020

Document Number:

698600194

FIELD INSPECTION FORM

Loc ID 312201 Inspector Name: St John, William (Cal) On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10352
Name of Operator: CM PRODUCTION LLC
Address: 390 UNION BLVD SUITE 620
City: LAKWOOD State: CO Zip: 80228

Findings:

10 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Hickey, Mike		michael.hickey@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
219440	WELL	PR	06/01/2012	OW	075-06347	MOUNT HOPE-GREEN (OWP) 31	TA

General Comment:

This is an orphaned well inspection. Inspection completed to document well status prior to start of plug and abandonment task.
Inspection may also identify possible task required for final closure/release of location from the Orphaned Well Program.
See link at end of report for path to downloadable pictures.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type:	Other	#	Comment:	Corrective Action:	Date:	corrective date
Type: Other		# 2	Comment: (2) electric conduit stub ups.	Corrective Action:	Date:	
Type: Deadman # & Marked		# 4	Comment: Located (4) anchors.	Corrective Action:	Date:	
Type: Ancillary equipment		# 1	Comment: Wellhead with tree and rod string.	Corrective Action:	Date:	
Type: Other		# 1	Comment: Concrete pump jack base.	Corrective Action:	Date:	
Type: Other		# 4	Comment: (3) wooden fence post and (1) power pole with power control box.	Corrective Action:	Date:	
Type: Flow Line		# 3	Comment: Located (3) risers.	Corrective Action:	Date:	

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 219440 Type: WELL API Number: 075-06347 Status: PR Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well is an Orphaned Well Program well. Valves at wellhead are closed and pumping unit has been removed.

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Well is scheduled for P&A. Removal of concrete base, power pole, and cleanup of production related debris is outside of scope of work and will require additional task to complete decommissioning/abandonment work of location.	stjohnw	01/03/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698600217	Inspection photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5033762