

# Interim Reclamation and Stormwater Inspection

February 13, 2020

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC -  
#8960

Location ID: 432395

Inspection Document #: 697501117

Weld County, CO

NWNW Section 26 T5N R63W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos

Location Name: State North Platte #F21-J24-26HNC

Location ID: 432395



**Photo 1.** Photo taken from the southern interim reclamation area, facing East. Photo illustrates weedy annual vegetation consisting mostly of Russian thistle with little to no desirable vegetation.



## Inspection Photos

Location Name: State North Platte #F21-J24-26HNC

Location ID: 432395



**Photo 2.** Photo taken from the southeastern interim area, facing East. See comments under Photo 1. Photo also illustrates weed debris in the perimeter fence.



Inspection Photos  
Location Name: State North Platte #F21-J24-26HNC  
Location ID: 432395



**Photo 3.** Photo taken from the southeastern interim area, facing East. Photo illustrates the interim area in contrast to the reference area vegetation.



## Inspection Photos

Location Name: State North Platte #F21-J24-26HNC

Location ID: 432395



**Photo 4.** Close up photo taken with the dense patch of Russian thistle. Photo illustrates a thick (~3-5") layer of Russian thistle thatch likely negatively affecting successful germination of desirable species.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Number: 697501117



Inspection Photos  
Location Name: State North Platte #F21-J24-26HNC  
Location ID: 432395



**Photo 5.** Photo taken from the southwestern interim area, facing West. See comments under Photo 1.





## Inspection Photos

Location Name: State North Platte #F21-J24-26HNC

Location ID: 432395



**Photo 6.** Photo taken from the southwestern interim area, facing North. See comments under Photo 1.