

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/06/2020

Submitted Date:

03/09/2020

Document Number:

699600307

FIELD INSPECTION FORM

Loc ID: 312201 Inspector Name: SCHURE, KYM On-Site Inspection: 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10352
Name of Operator: CM PRODUCTION LLC
Address: 390 UNION BLVD SUITE 620
City: LAKEWOOD State: CO Zip: 80228

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Hickey, Mike		michael.hickey@state.co.us	
Quint, Craig		craig.quint@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
219440	WELL	PR	06/01/2012	OW	075-06347	MOUNT HOPE-GREEN (OWP) 31	PA

General Comment:

OWP Project - Assisting OWP supervising removal of tanks @ battery. Contractor arrived on location a designated time. Safety meeting with daily work plan performed. CO tank #2 has been loaded and removed from location. PW tank + CO tank #1 + CO tank #2 have been removed from location. Contents of tanks have been transported for disposal. (1) PBV plastic PW overflow tank remains within berms @ tank battery. Berms remain in place. Contractor collected/loaded and hauled off scrap iron and debris. Contractor has exited location with all described work performed. SATISFACTORY

Location

Lease Road:			
Type	Access		
comment:	Two track grassland		
Corrective Action:		Date:	

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:	Signage was unreadable and was inadvertently removed by contractor as debris.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	N/A		
Corrective Action:		Date:	

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	Removed from location		
Corrective Action:		Date:	

Tanks and Berms:						
Contents	#	Capacity	Type	Tank ID	SE GPS	
Comment:	PW tank and CO tanks #1 & 2 have been removed from locaton. (1) PBV plastic PW overflow tank remains on location within berms.					
Corrective Action:						Date:

Paint

Condition	<input style="width: 100%;" type="text"/>
Other (Content)	<input style="width: 100%;" type="text"/>
Other (Capacity)	<input style="width: 100%;" type="text"/>
Other (Type)	<input style="width: 100%;" type="text"/>

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:	Berms remain in place @ battery site.			
Corrective Action:				
			Date:	

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 219440 Type: WELL API Number: 075-06347 Status: PR Insp. Status: PA

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	In Process	Other	In Process			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
OWP Project - Assisting with supervision of removal of tanks @ battery. (1) PW tank (300) bbl. & (2) CO tanks (300) bbl. ea. removed. Debris and trash hauled off location. All waste product has been transported for disposal. SATISFACTORY	schureky	03/09/2020