

# Interim Reclamation and Stormwater Inspection

March 5, 2020

Operator: NOBLE ENERGY INC- #100322

Location ID: 449370

Inspection Document #: 697501223

Weld County, CO

NWSW Section 21 T6N R64W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: A21 /Tank  
Location ID: 449370



**Photo 1.** Photo taken from the western production facility location, facing South. Photo illustrates the production equipment in relation to the western disturbance area. It does not appear the Operator can reduce the size of the location any further.



**Photo 2.** Photo taken from the western production facility location, facing North. See comments under Photo 1.

Also, photo illustrates the western portion of this location is cut.



Inspection Photos  
Location Name: A21 /Tank  
Location ID: 449370



**Photo 3.** Photo taken from the northwestern production facility location, facing East. See comments under Photo 1.

Also, photo illustrates the northern portion of this location is cut.



**Photo 4.** Photo taken from the northern production facility location, facing East. See comments under Photo 1.



Inspection Photos  
Location Name: A21 /Tank  
Location ID: 449370



**Photo 5.** Photo taken from the northeastern production facility location, facing South. See comments under Photo 1.



**Photo 6.** Photo taken from the eastern production facility location, facing South. Photo illustrates a retention area with a stabilized outlet (southeastern corner).

Also, photo illustrates the eastern portion is fill.



Inspection Photos  
Location Name: A21 /Tank  
Location ID: 449370



**Photo 7.** Photo taken from the southeastern production facility location, facing Southeast. Photo illustrates a stabilized outlet.



**Photo 8.** Photo taken from the southeastern production facility location, facing West. Photo illustrates a ditch and berm along the southern location that is directed to a stabilized outlet.

Also, photo illustrates the southern portion is fill.



Inspection Photos  
Location Name: A21 /Tank  
Location ID: 449370



**Photo 9.** Photo taken from the southern production facility location, facing East. See comments under Photo 8.