

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/18/2020

Submitted Date:

03/19/2020

Document Number:

700400548

**FIELD INSPECTION FORM**

Loc ID: 315090      Inspector Name: Moran, Rick      On-Site Inspection:       2A Doc Num: \_\_\_\_\_

**Status Summary:**

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

5 Number of Comments

1 Number of Corrective Actions

Corrective Action Response Requested

**Operator Information:**

OGCC Operator Number: 10654

Name of Operator: LASSO OIL & GAS LLC

Address: 3021 RIDGE RD #156

City: ROCKWALL      State: TX      Zip: 75032

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
Freeman, Kris	254-717-0435	kfreeman@31operating.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230238	WELL	SI	01/01/2017	OW	103-07897	FEDERAL 1-17	TA

**General Comment:**

COGCC Inspection Report Summary.

On 3-18-2020 at approximately 14:00, inspector Rick Moran, conducted a routine inspection at Lasso Oil & Gas well Federal 1-17 in Rio Blanco county.

The following compliance issues were observed:

1) Missing "911" on lease road sign located 4 miles from well. Photo 7. Complete by 4-19-2020.

Note: Warning letter 401967037 dated 3-11-2019 for no current MIT.

A follow up inspection will occur to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 700400548.

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Missing "911" on lease road sign located 4 miles from well.	Date:	04/19/2020
Corrective Action:	Install sign to comply with Rule 210.b.		

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	PIT		
Comment:			
Corrective Action:		Date:	

**Equipment:**

Type			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		

Comment: Pump jack head & tubing lying on ground.		Date:
Corrective Action:		Date:
Type: Ancillary equipment	# 1	
Comment: Propane tank.		Date:
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:		Date:			

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:				
Corrective Action:		Date:		

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:		Date:			

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:				
Corrective Action:		Date:		

**Venting:**

Yes/No	NO	Date:
Comment:		Date:
Corrective Action:		Date:

**Flaring:**

Type	
------	--

Comment:		
Corrective Action:	Date:	

**Inspected Facilities**

Facility ID: 230238 Type: WELL API Number: 103-07897 Status: SI Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Last recorded production July 2017. No MIT on file.  
No current MIT on record or delinquent as required by Rule 326

Corrective Action:

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass					

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

Type: Blowdown                      Lined:                      Pit ID:                      Lat:                      Long:

Reference Point: \_\_\_\_\_                      Other: \_\_\_\_\_                      Length: \_\_\_\_\_                      Width: \_\_\_\_\_

**Lining:**

Liner Type:    Liner Condition:

Comment:

Corrective Action

Date:

**Fencing:**

Fencing Type: Wildlife    Fencing Condition: Adequate

Comment:

Corrective Action

Date:

**Netting:**

Netting Type: Mesh    Netting Condition: Good

Comment:

Corrective Action

Date:

Anchor Trench Present:                      Oil Accumulation: NO                      2+ feet Freeboard: YES

Comment:

Corrective Action

Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402347759	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5100779">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5100779</a>
700400549	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5100771">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5100771</a>