

Inspection Photos  
Operator: Dugan Production  
API#: 067-06497  
Date: 4/3/2020



Photo 1. View of the eastern project area from the northeastern corner facing southward. Revegetation is progressing with grasses such as Indian ricegrass and shrubs such as rubber rabbitbrush and antelope bitterbrush.





Photo 2. View of area where debris was identified in 2018 reclamation inspection. Debris is no longer present.





Photo 3. View of the western project area from the northwestern corner facing southward.





Photo 4. View of reference area vegetation comprised of pinyon-juniper woodland with shrubs such as antelope bitterbrush and sagebrush, and forbs such as Indian ricegrass.